





Testing. Advising. Assuring.

<b>EWFA TEST REPORT</b>	<b>Test Report No : 29178100.1 Page 1 of 1</b>
-------------------------	--

Report Sponsor	Issue Date
Talbot Automatic Doors and Gates Unit 8, 63 Nomran Street, PEAKHURST NSW 2210	04/02/2015
Test Period	Test Standard
11/06/2014 to 21/01/2015	AS 5007-2007 Clause 4.4.1.1 – Endurance test and 4.4.2 Mains Power failure.
Description of Specimen	
<b>Door Operator</b>	Talbot Sliding Door Operator Model No: DSH-250
<b>Door Configuration</b>	The door operator assembly mounted on a steel support frame operated as a Bi parting sliding door system with a total combined door mass of 260 kg.
	

Test Results	
AS5007-2007 Clause 4.4.1.1 Normal Operation ( for BCA Class 1B, 2 to 9 building ) Clause 4.4.1.1 a) 1 000 000 cycles under normal environmental* conditions Clause 4.4.1.1 b) 1 000 cycles under -15°C±3°C environmental conditions Clause 4.4.1.1 c) 1 000 cycles under +50°C environmental conditions Clause 4.4.2 (a) 40 cycles when subjected to mains power failure	Pass Pass Pass Pass
<i>(*The normal environmental conditions for this test were outside 20+5°C however it was conducted under indoor ambient laboratory conditions with a minimum and maximum temperature of 6°C and 44°C respectively)</i>	

 Accreditation No 3277 Accredited for compliance with ISO/IEC 17025	<b>TESTING AUTHORITY</b>	Exova Warringtonfire Aus Pty Ltd
	<b>Laboratory Address</b>	PO Box 4282 DANDENONG SOUTH VIC 3164 Unit 2, 409-411 Hammond Road DANDENONG VIC 3175
	<b>Phone / Fax</b>	61 (0)3 9767 1000 / 61 (0)3 9767 1001
	<b>ABN</b>	81 050 241 524
	<b>Email / Home Page</b>	<a href="http://www.exova.com">www.exova.com</a>
	Prepared by:  Steven Halliday Fire Test Engineer	Reviewed by:  Chad McLean Approved Signatory